	Define	Map the current situation	Find the root cause	Set your target	Implement improvement	Secure succes
				Create		
Lean	Identify value	Map the current situation		Flow	Create pull	Perfection
6σ	Define	Measure	Ana	lyse	Improve	Control
TOC	Identify the constrain		Exploit		Elevate	Repeat the process
			Find the	Generate a		
TQM	Identify the problem		root cause	solution	Plan and improve	Measure and standerdize

Tabel 2